








Map Legend

-  Controller
-  Remote Control Valve
-  Backflow Device
-  Shrub Spray
-  Pipe (Lateral)
-  Background Areas



Sample Site Inspection Report

Notes:
 This is a sample of a site inspection report showing repairs that are being proposed. Contractors would enclose this report with their bid.



Project: System Inspection	
Location: Logan, Utah	
Client Name: Landscape Company	
10/2/2012 3:45:53 PM	Revision: 3
Created by: Jim	Approved by: Jim
Disclaimer:	
11 x 17	1/3

Parts List Summary

Label	Manufacturer	What is the condition	Part Description	Part Number	Series
Backflow Device Problem	Wilkins	Installed Backwards	Reduced Pressure Backflow Preventer, 2-1/2" & 3"	475	475
Leaking Control Valve	Irritrol		1", globe configuration, NPT threads	205T	205
Controller Problem	Hunter		12 stations, indoor model, 240V, for Australian ma	PCC-1201iA	Pro-C Conv. International
Lateral Line Leak	Charlotte		1" PVC Schedule 40	PVC 05007B	1" x 20' PVC DWV Schedule 40 Pipe
Dry Terf Area					
Broken Shrub Spray 1	Hunter		6" popup w/ drain check valve	INST-06-CV	Insitucional Spray
Broken Shrub Spray 2	Hunter		6" popup w/ drain check valve	INST-06-CV	Insitucional Spray

Sample Site Inspection Report

Notes:
This is a sample of a site inspection report showing repairs that are being proposed. Contractors would enclose this report with their bid.



Project: System Inspection	
Location: Logan, Utah	
Client Name: Landscape Company	
10/2/2012 3:45:53 PM	Revision: 3
Created by: Jim	Approved by: Jim
Disclaimer:	
11 x 17	2/3



2012-10-02 20:42Z
 Lat: 41° 45' 47.5056" N
 Lon: 111° 51' 42.0948" W
 snapped

Leaking Control Valve



2012-10-02 20:39Z
 Lat: 41° 45' 48.4968" N
 Lon: 111° 51' 42.5052" W
 snapped

Dry Turf Area

Sample Site Inspection Report

Notes:
 This is a sample of a site inspection report showing repairs that are being proposed. Contractors would enclose this report with their bid.

juniperaspect™
 [field mapping solutions]

Project: System Inspection	
Location: Logan, Utah	
Client Name: Landscape Company	
10/2/2012 3:45:53 PM	Revision: 3
Created by: Jim	Approved by: Jim
Disclaimer:	
8 1/2 x 11	3/3