

Release Notes for Version 1.7.4 of Windows® Embedded Handheld 6.5 for the Archer 2

May 2016

These notes provide important information for Juniper Systems release of the Microsoft Windows Embedded Handheld (formerly Windows Mobile) 6.5 operating system for the Archer 2. These notes may also include important hardware information for the device.

Documentation and software updates are available from:

<http://www.junipersys.com/Juniper-Systems/support>

Contents

These release notes contain the following sections:

- Important Notes
- Known Issues
- Resolved Issues

Important Notes

- **Encrypted SD card cannot be used for OS update.** The device cannot perform an OS update with an SD card that has been encrypted. Before running an OS update, verify that the encryption option in Start > Settings > System > Encryption is disabled.
- **Hardware OK button.** The shift-5 button on the keypad can be used to send an "OK" to the application for screens that may not display an OK button and screens where the OK button does not work. This is most useful in applications that were designed for an earlier version of Windows Mobile, and it can also be found on some of the built-in applets.

Known Issues

These issues are open in this version of the Operating System.

Battery / Charging

- Under some conditions the unit may wake from suspend while it is charging. [7348] Turn on auto suspend enabled so that it will return to suspend mode. Settings > system > power > advanced > On external power:

Resolved Issues

These issues are resolved in this version of the Operating System.

- The AKU was updated to integrate fixes from Microsoft, such as a fix to support SHA-2.
- Updated GNSS control panel to handle differences between U-Blox and NVS GNSS receivers.
- Updated System control panel to indicate which receiver is detected.
- Updated JSNav to version 1.3.0 – translation updates for various languages (GNSS control panel and JSNAV).
- Added the ability to adjust the duration of the touchscreen disable notification.
- The links for *hold to zoom* functionality in Spanish and Portuguese have been fixed.
- USB PCL (3.0 or previous) printing functionality has been fixed.
- GNSS control panel has been updated to add the GST sentence.
- The default settings for GNSS constellations have been updated.

PN 24286-06. © Copyright 2016. Juniper Systems, Inc. All rights reserved.

ActiveSync, Windows, and Windows Mobile are registered trademarks of Microsoft, Inc. in the United States and/or other countries.

Other trademarks in this document are the property of their respective owners.