

Release Notes

LandMark Mobile from Juniper Systems, Inc.

P/N: 20528-02

Product Description: LandMark Mobile is a GPS utility program designed to operate in the Windows Mobile environment.

System Requirements: Juniper Systems Field PC running Windows Mobile 5.0 or 6.1

Version: 1.0.7

Release date: July 2011.

New Features: Bug Fix release

Important Notes: LandMark Mobile is a GPS utility program providing multiple data interfaces to other programs running concurrently, navigation, and waypoint data collection. See user's manual for addition features.

Upgrade Instructions: N/A

Resolved Issues: This release added the Insert and Delete keys back in to be used as Hot Keys. This functionality was missing from version 1.0.6.

Open Issues:

LandMark Mobile may incorrectly report that a WAAS satellite is not being used for differential correction. This issue only appears with certain receivers. The user can determine if differential correction is used by checking the GPS status screen and verifying that it reports "3D Diff," or by checking the diagnostics screen and verifying that Quality is "2."

When this issue appears, other indicators such as "W1/W2" may be reporting incorrect information. [M1481]

For sub-meter receivers, the precision indicated by EHE may be better than the value reported by LandMark Mobile. Although EHE may be reported as about 3 meters, the actual positions captured will be within the sub-meter accuracy of the receiver, provided that the conditions for the receiver to function at high accuracy are met. [M1482]

Issues Closed without Resolution: N/A